



SDS

GHS Safety Data Sheet

PROFILE Products, LLC

F-4 Netless™

MSDS Number: CON043

Revision Date: 1/1/14

Page 1 of 4

PRODUCT AND COMPANY IDENTIFICATION

Manufacturer

PROFILE Products, LLC
750 LAKE COOK ROAD
SUITE 440
BUFFALO GROVE, IL 60089

Product Name: F-4 Netless™
Revision Date: 1/1/14
MSDS Number: CON043
Common Name: N.A.

Description-Pine/Poplar Wood Fiber Mat with synthetic fibers

HAZARDS IDENTIFICATION

Route of Entry: Inhalation, skin contact, eye contact


Inhalation: Wood dust may cause sneezing, irritation, and dryness of the nose and throat. Dust may aggravate pre-existing respiratory conditions.

Skin Contact: Wood dust can cause irritation. Skin absorption is not known to occur.

Eye Contact: Wood dust can irritate the eyes.

Ingestion: No reports of human ingestion.

NFPA: Health = 0, Fire = 1, Reactivity = 0



Avoid inhalation of any dust, avoid skin contact, protect eyes, avoid ingestion and prolonged exposure.

COMPOSITION/INFORMATION ON INGREDIENTS



SDS

GHS Safety Data Sheet

PROFILE Products, LLC

F-4 Netless™

MSDS Number: CON043

Revision Date: 1/1/14

Page 2 of 4

Ingredients:

Cas #	Perc.	Chemical Name

4 FIRST AID MEASURES

- Inhalation:** Usually not a problem. Remove to fresh air if respiratory irritation develops, and get medical aid promptly if irritation persists.
- Skin Contact:** Usually not a problem. Wash off with running water if irritation is experienced.
- Eye Contact:** Open eyelids and flush with water.
- Ingestion:** Get medical attention.

FIRE FIGHTING MEASURES

Autoignition Temp: 200-260°C (400-500°F)

Flammable- Extinguish with water; same as a wood fire

6 ACCIDENTAL RELEASE MEASURES

Sprinkle spillage compound to minimize dust and sweep up spilled debris, absorb and sweep up / collect; avoid inhalation and / or ingestion of any dust.

HANDLING AND STORAGE

- Handling Precautions:** Do not store in contact with flames or hot surfaces.
- Storage Requirements:** Store in a cool, dry place. Keep away from sources of ignition.

8 EXPOSURE CONTROLS/PERSONAL PROTECTION

- Personal Protective Equip:** Eyes: Safety glasses or goggles should be worn if there is possibility of eye contact.
Skin: Gloves for hands, wear clothing to prevent skin contact.

9 PHYSICAL AND CHEMICAL PROPERTIES

- Appearance:** Green or Natural Brown non-woven mat
- Spec Grav./Density:** Lighter than water
- Vapor Pressure:** N/A
- Odor:** Wood odor



SDS

GHS Safety Data Sheet

PROFILE Products, LLC

F-4 Netless™

MSDS Number: CON043

Revision Date: 1/1/14

Page 3 of 4

10	STABILITY AND REACTIVITY
----	---------------------------------

Stability: Stable
Materials to Avoid: Avoid strong oxidizers/reducers
Hazardous Polymerization: Will not occur.

11	TOXICOLOGICAL INFORMATION
----	----------------------------------

Wood dusts- All other species: ACGIH (2007): TLV-TWA 1 mg/m³ (Inhalable fraction); A4
Particulates Not Otherwise Regulated (PNOR): OSHA: PEL-TWA 15 mg/m³ (Total Dust); 5 mg/m³ (Respirable fraction)

12	ECOLOGICAL INFORMATION
----	-------------------------------

48-hr LC₅₀ = >100% for Daphnia magna when runoff generated using ASTM D7101 (2"/hr rainfall rate) was tested according to EPA-821-R-02-012.

13	DISPOSAL CONSIDERATIONS
----	--------------------------------

Disposal according to local, state and federal environmental requirements.

14	TRANSPORT INFORMATION
----	------------------------------

DOT Class: Not regulated #



SDS

GHS Safety Data Sheet

PROFILE Products, LLC

F-4 Netless™

MSDS Number: CON043

Revision Date: 1/1/14

Page 4 of 4

REGULATORY INFORMATION

COMPONENT / (CAS/PERC) / CODES

REGULATORY KEY DESCRIPTIONS

MASS = MA Massachusetts Hazardous Substances List
NRC = Nationally Recognized Carcinogens
OSHA WAC = OSHA Workplace Air Contaminants
PA = PA Right-To-Know List of Hazardous Substances
TXAIR = TX Air Contaminants with Health Effects Screening Level

CERCLA = Superfund clean up substance
CSWS = Clean Water Act Hazardous substances
EHS302 = Extremely Hazardous Substance
EPCRAWPC = EPCRA Water Priority Chemicals
HAP = Hazardous Air Pollutants
NJEHS = NJ Extraordinarily Hazardous Substances
NJHS = NJ Right-to-Know Hazardous Substances
OSHA PSM = OSHA Chemicals Requiring process safety management
SARA313 = SARA 313 Title III Toxic Chemicals

OTHER INFORMATION